Auckland: (09) 2717 234
Christchurch: (03) 741 6241

sales@machineryhouse.co.nz
www.machineryhouse.co.nz

Product Brochure For W149

Magswitch Welding Ground Clamps - 600 amp

Back In Stock Soon

Ex GST	Inc GST
$144.00	$165.60

ORDER CODE:	W149
Amperage Size (amp):	600
Type:	Magswitch



Description

Magswitch Welding Ground Clamps
Saves welders time & money!
The convenience of a magnetic ground without the hassle!

Switchable Magnetic Ground Clamp
Rated up to 600 amp
Fast, convenient ground
Strong magnets for a great hold
After use, switch off and wipe clean

Unique design
Perfect for sheet, plate & pipe applications has easy connect and release with on/off knob.

Cuts set-up time
No more tacking on & grinding off tabs.
Simply turn off the Magswitch & wipe away debris for a fast clean finish.

Surface preparation:
1. Surface preparation is critical to a good ground when welding. Be certain that a "bare metal" area is cleared for attachment of the Magswitch Ground Clamp. Failure to do so could result in an arc situation.
2. Magswitch Ground Clamp works only with ferrous metals.

To attach clamp:
1. Be sure magnet is in the "OFF" position. Works on pipe or flat surface.
2. Be sure surface is bare steel - clear away any debris.
3. Place clamp to surface. Turn Magswitch knob clockwise to "ON" position - a full 185º degrees.

To remove clamp:
1. Turn Magswitch knob to the "OFF" position by rotating counterclockwise.
2. Wipe away debris from the clamp.

Auckland: (09) 2717 234
Christchurch: (03) 741 6241

sales@machineryhouse.co.nz
www.machineryhouse.co.nz

Product Brochure For W149

Recommended Accessories

W100
ROGUE™ Heavy Duty Welding Gloves - 400mm

