

Product Brochure For W148

Magswitch Welding Ground Clamps - 300 amp

ORDER CODE:	W148
Amperage Size (amp):	300
Type:	Magswitch

**Description**

Magswitch Welding Ground Clamps
Saves welders time & money!
The convenience of a magnetic ground without the hassle!

Switchable Magnetic Ground Clamp
Rated up to 300 amp
Fast, convenient ground
Strong magnets for a great hold
After use, switch off and wipe clean

Unique design
Perfect for sheet, plate & pipe applications
Has easy connect and release with on/off knob

Cuts set-up time
No more tacking on & grinding off tabs
Simply turn off the Magswitch & wipe away debris for a fast clean finish

Surface preparation:
1. Surface preparation is critical to a good ground when welding. Be certain that a "bare metal" area is cleared for attachment of the Magswitch Ground Clamp. Failure to do so could result in an arc situation.
2. Magswitch Ground Clamp works only with ferrous metals.

To attach clamp:
1. Be sure magnet is in the "OFF" position. Works on pipe or flat surface.
2. Be sure surface is bare steel - clear away any debris.
3. Place clamp to surface. Turn Magswitch knob clockwise to "ON" position - a full 185° degrees.

To remove clamp:
1. Turn Magswitch knob to the "OFF" position by rotating counterclockwise.
2. Wipe away debris from the clamp.

Product Brochure For W148

Specific Features



Packaging

Recommended Accessories

W100

ROGUE™ Heavy Duty Welding
Gloves - 400mm

